

# Property History

Permits, licenses, violations & appeals by address

[L&I dashboard](#) / [Property history](#) / [2129 N 5TH ST](#) / [Permit: 932318](#)

MECHANICAL PERMIT

**ISSUED** 12/04/2018

## 932318

**L&I District: CENTRAL EAST**

**OPA Account #: 191295000**

2129 N 5TH ST

Philadelphia, PA 19122-1411

<b>L&amp;I district</b>	CENTRAL EAST
<b>Permit number</b>	932318
<b>Permit type</b>	MECHANICAL PERMIT (BP_MECH)
<b>Type of work</b>	APPL INSTALL TWO SYSTEMS WITH 2 60K BTUS @90% AND 2 TWO TOI A/C UNITS ALL DUCT WORK
<b>Permit status</b>	COMPLETED
<b>Date issued</b>	Dec. 04, 2018
<b>Zoning documents</b>	No zoning documents
<b>Contractor</b>	SS MECHANICALS HVAC 1326 OAK LANE AVENUE PHILADELPHIA PA 19126-

## Property History

Permits, licenses, violations & appeals by address