



[CLICK HERE TO SIGN UP FOR BUILDINGS NEWS](#)

NYC Department of Buildings
Property Profile Overview

114 WEST 72 STREET

MANHATTAN 10023

BIN# 1029891

WEST 72 STREET 114 - 116

Health Area : 4000
Census Tract : 157
Community Board : 107
[Buildings on Lot](#) : 2

Tax Block : 1143
Tax Lot : 37
Condo : NO
Vacant : NO

[View DCP Addresses...](#) [Browse Block](#)

[View Zoning Documents](#) [View Challenge Results](#) [Pre - BIS PA](#) [View Certificates of Occupancy](#)

Cross Street(s): COLUMBUS AVENUE, AMSTERDAM AVENUE
DOB Special Place Name:
DOB Building Remarks:
Landmark Status: L - LANDMARK Special Status: N/A
Local Law: YES Loft Law: NO
SRO Restricted: NO TA Restricted: NO
UB Restricted: NO
Environmental Restrictions: N/A Grandfathered Sign: NO
Legal Adult Use: NO City Owned: NO
Additional BINs for Building: NONE
HPD Multiple Dwelling: Yes
Number of Dwelling Units: 69

Special District: UNKNOWN

This property is not located in an area that may be affected by Tidal Wetlands, Freshwater Wetlands, Coastal Erosion Hazard Area, or Special Flood Hazard Area. [Click here for more information](#)

Department of Finance Building Classification: D4-ELEVATOR APT

Please Note: The Department of Finance's building classification information shows a building's tax status, which may not be the same as the legal use of the structure. To determine the legal use of a structure, research the records of the Department of Buildings.

	Total	Open	Elevator Records
Complaints	29	0	Electrical Applications
Violations-DOB	85	3	Permits In-Process / Issued
Violations-OATH/ECB	31	4	Illuminated Signs Annual Permits
Jobs/Filings	18		Plumbing Inspections
ARA / LAA Jobs	5		Open Plumbing Jobs / Work Types
Total Jobs	23		Facades
Actions	98		Marquee Annual Permits
OR Enter Action Type: <input type="text"/>			Boiler Records
OR Select from List: <input type="text" value="Select..."/>			DEP Boiler Information
AND <input type="button" value="Show Actions"/>			Crane Information
			After Hours Variance Permits