

Property Information		Request Information		Update Information	
File#:	BS-X01693-12734073	Requested Date:	07/17/2024	Update Requested:	
Owner:	WILLIAM KUESTER	Branch:		Requested By:	
Address 1:	213 ROCK ST	Date Completed:	07/30/2024	Update Completed:	
Address 2:	UNIT K3	# of Jurisdiction(s):			
City, State Zip:	: NORWOOD, MA	# of Parcel(s):	1		

Notes

CODE VIOLATIONS Per Town of Norwood Department of Zoning there are no Code Violation cases on this property

Collector: Town of Norwood Department of Zoning

Payble Address: 566 Washington Street, Ground Floor, Room 8, Norwood, MA 02062

Business: 781-762-1240

UNABLE TO PROVIDE DOCUMENTATION TO THIRD PARTIES. VERBAL INFO ACQUIRED

PERMITS Per Town of Norwood Building Department There are no Open/Pending/Expired Permit on this Property.

Collector: Town of Norwood Building Department

Payble Address: 566 Washington Street, Ground Floor, Room 8, Norwood, MA 02062

Business: 781-762-1240

SPECIAL ASSESSMENTS Per City of Norwood Tax Collector there are no Special Assessments/liens on the property.

Collector: Town of Norwood Tax Collector

Payble Address: 566 Washington St, Norwood, MA 02062

Business: 781-762-1240

UNABLE TO PROVIDE DOCUMENTATION TO THIRD PARTIES. VERBAL INFO ACQUIRED

DEMOLITION NO

UTILITIES WATER AND SEWER

MASTER METER PAID BY HOA

Collector: Town of Norwood Water and Sewer Services Payable Address: 566 Washington St. Norwood, MA 02062

Business # 781-762-5180

GARBAGE

GARBAGE PRIVATE HAULER WITH LIEN STATUS AND BALANCE UNKNOWN

213-K3 ROCK STREET

Location 213-K3 ROCK STREET **Mblu** 18/ 16/ 3/ 60/

Acct# Owner KUESTER, WILLIAM F

Assessment \$273,900 **Appraisal** \$273,900

Building Count 1

Current Value

Appraisal					
Valuation Year Improvements Land Total					
2024	\$273,900	\$0	\$273,900		
	Assessment				
Valuation Year	Improvements	Land	Total		
2024	\$273,900	\$0	\$273,900		

Owner of Record

Owner KUESTER, WILLIAM F Sale Price \$186,000

Co-Owner Certificate

 Address
 213-K3 ROCK STREET
 Book & Page
 26089-199/0

 NORWOOD, MA 02062
 Sale Date
 10/10/2008

Instrument 00

Ownership History

Ownership History							
Owner Sale Price Certificate Book & Page Instrument Sale Date							
KUESTER, WILLIAM F	\$186,000		26089-199/0	00	10/10/2008		
TARQUINI, JOHN J	\$150,000		16693/0112	00	06/03/2002		
GALLAHUE, MICHAEL P &	\$95,000		07534/0581	00	04/22/1987		

Building Information

Building 1: Section 1

Year Built:1970Living Area:443Replacement Cost:\$385,753Building Percent Good:71

Replacement Cost

Less Depreciation: \$273,900

Building Attributes				
Field	Description			
Style:	Condo Res			
Model	Res Condo			
Stories:	1 Story			
Grade	Average			
Occupancy	1			
Interior Wall 1:	Plastered			

Building Photo



(https://images.vgsi.com/photos/NorwoodMAPhotos/\\00\\00\\71\\28.jpg)

Interior Wall 2:	
Interior Floor 1	Hardwood
Interior Floor 2	Carpet
Heat Fuel:	Gas
Heat Type:	Hot Water
AC Type:	None
Ttl Bedrms:	2 Bedrooms
Ttl Bathrms:	1 Full
Ttl Half Bths:	0
Xtra Fixtres	
Total Rooms:	4
Bath Style:	Average
Kitchen Style:	Modern
Kitchen Type	00
Kitchen Func	00
Primary Bldg Use	
Htwtr Type	00
Atypical	
Park Type	N
Park Own	N
Park Tandem	N
Fireplaces	
Num Part Bedrm	
Base Flr Pm	
Num Park	00
Pct Low Ceiling	
Unit Locn	
Grade	Average
Stories:	2
Residential Units:	69
Exterior Wall 1:	Brick Veneer
Exterior Wall 2:	
Roof Structure	Gable/Hip
Roof Cover	Asph/F Gls/Cmp
Cmrcl Units:	0
Res/Com Units:	0
Section #:	1
Parking Spaces	0
Section Style:	0
Foundation	
Security:	
Cmplx Cnd	
Xtra Field 1:	
Remodel Ext:	
Super	

Building Layout

FB[885]	7

(https://images.vgsi.com/photos/NorwoodMAPhotos//Sketches/13947_145;

Building Sub-Areas (sq ft) <u>Le</u>			
Code	Description Gross		Living Area
SFB	Base, Semi-Finished	885	443
		885	443

Extra Features

Grade

No Data for Extra Features

Land

Land Use		Land Line Valua	Land Line Valuation	
Use Code	1021	Size (Acres)	0	
Description	CONDO RES	Frontage	0	
Zone		Depth	0	
Neighborhood		Assessed Value	\$0	
Alt Land Appr	No	Appraised Value	\$0	
Category				

Outbuildings

Outbuildings	<u>Legend</u>
No Data for Outbuildings	

Valuation History

Appraisal				
Valuation Year	Improvements	Land	Total	
2023	\$251,600	\$0	\$251,600	
2022	\$227,700	\$0	\$227,700	
2021	\$215,900	\$0	\$215,900	

Assessment					
Valuation Year Improvements Land Total					
2023	\$251,600	\$0	\$251,600		
2022	\$227,700	\$0	\$227,700		
2021	\$215,900	\$0	\$215,900		

(c) 2024 Vision Government Solutions, Inc. All rights reserved.

FW: Code/permit/Special assessment Request / 213 ROCK STREET UNIT K3

.

1 attachments (120 KB)

213 Rock Street Permit history.pdf;

From: Katrina Fahy <kfahy@norwoodma.gov>

Sent: Friday, July 26, 2024 9:28 PM

To:

Subject: Fwd: Code/permit/Special assessment Request / 213 ROCK STREET UNIT K3

Good morning,

Attached, please find the permit history for 213 Rock Street. There are no open permits on the property.

Thank you, Katrina

All Permits Summary Report

Туре	Permit No	Date I	full Description	Open Text	Status
21	13 ROCK	STREET			
ELECTRICAL	131368	9/27/2017	CONDO: REPLACE F/A/ PANEL & DETECTION		APPLICATION
ELECTRICAL	131125	8/29/2017	SECURITY SYSTEM ADD ON. ONE WIRED CONTACT.		APPLICATION
ELECTRICAL	130440	5/30/2017	REWIRE KITCHEN AND BATHROOM. REPLACE 911 DEVICES IN UNIT, REWIRE EXISTING LIGHT FIXTURES.		COMPLETED
BUILDING	130427	5/26/2017	RENOVATE EXISTING KITCHEN & BATHROOM. REPLACE FLOORING THROUGHOUT UNIT. PAINT ENTIRE UNIT.		COMPLETED
GAS	119278	8/13/2013	WATER HEATER		COMPLETED
ELECTRICAL	117574	12/10/2012	COPALUM ALUMINUM REPAIRS		COMPLETED
ELECTRICAL	117575	12/10/2012	COPALUM ALUMINUM REPAIRS		COMPLETED
ELECTRICAL	117576	12/10/2012	COPALUM ALUMINUM REPAIRS		COMPLETED
ELECTRICAL	117577	12/10/2012	COPALUM ALUMINUM REPAIRS		COMPLETED
ELECTRICAL	117578	12/10/2012	COPALUM ALUMINUM REPAIRS		COMPLETED
ELECTRICAL	117579	12/10/2012	COPALUM ALUMINUM REPAIRS		COMPLETED
ELECTRICAL	117580	12/10/2012	COPALUM ALUMINUM REPAIRS		COMPLETED
ELECTRICAL	117581	12/10/2012	COPALUM ALUMINUM REPAIRS		COMPLETED
ELECTRICAL	117582	12/10/2012	COPALUM ALUMINUM REPAIRS		COMPLETED

 $[\]mbox{\ensuremath{\star}}$: Asterik after permit means there are notes on inspection

Thursday, June 29, 2023 Page 1 of 4

Type	Permit No	Date	Full Description	Open Text	Status
ELECTRICAL	117583	12/10/2012	COPALUM ALUMINUM REPAIRS		COMPLETED
ELECTRICAL	117584	12/10/2012	COPALUM ALUMINUM REPAIRS		COMPLETED
ELECTRICAL	117585	12/10/2012	COPALUM ALUMINUM REPAIRS		COMPLETED
GAS	116318	7/24/2012	HEATING BOILER		COMPLETED
BUILDING	112573	5/6/2011	REMODEL KITCHEN AND BATH - NO STRUCTURAL CHANGES		APPLICATION
GAS	104029	2/19/2008	WATER HEATER		APPLICATION
GAS	103785	1/28/2008	HEATING BOILER	HEATING BOILER	APPLICATION
ELECTRICAL	63527	7/22/2004	SECURITY SYSTEMS		APPLICATION
GAS	41651	3/13/1997	WATER HEATER	W.H. IN BASEMENT	COMPLETED
ELECTRICAL	41618	3/11/1997	APT. K-1, REPLACE PANELS IN UNITS/INSP. + REPAIR ALUMINUM CIRCUITS [IF FOUND IN UNIT]		COMPLETED
ELECTRICAL	41619	3/11/1997	APT. K-2, REPLACE PANELS IN UNITS/INSP. + REPAIR ALUMINUM CIRCUITS [IF FOUND IN UNIT]		COMPLETED
ELECTRICAL	41620	3/11/1997	APT. K-3, REPLACE PANELS IN UNITS/INSP. + REPAIR ALUMINUM CIRCUITS [IF FOUND IN UNIT]		COMPLETED
ELECTRICAL	41621	3/11/1997	APT. K-4, REPLACE PANELS IN UNITS/INSP. + REPAIR ALUMINUM CIRCUITS [IF FOUND IN UNIT]		COMPLETED
ELECTRICAL	41622	3/11/1997	APT. K-5, REPLACE PANELS IN UNITS/INSP. + REPAIR ALUMINUM CIRCUITS [IF FOUND IN UNIT]		COMPLETED
ELECTRICAL	41623	3/11/1997	APT. K-6, REPLACE PANELS IN UNITS/INSP. + REPAIR ALUMINUM CIRCUITS [IF FOUND IN UNIT]		COMPLETED

$\mbox{\ensuremath{\star}}$: Asterik after permit means there are notes on inspection

Thursday, June 29, 2023 Page 2 of 4

Туре	Permit No	Date	Full Description	Open Text	Status
ELECTRICAL	41624	3/11/1997	APT. K-7, REPLACE PANELS IN UNITS/INSP. + REPAIR ALUMINUM CIRCUITS [IF FOUND IN UNIT]		COMPLETED
ELECTRICAL	41625	3/11/1997	APT. K-8, REPLACE PANELS IN UNITS/INSP. + REPAIR ALUMINUM CIRCUITS [IF FOUND IN UNIT]		COMPLETED
ELECTRICAL	41626	3/11/1997	APT. K-9, REPLACE PANELS IN UNITS/INSP. + REPAIR ALUMINUM CIRCUITS [IF FOUND IN UNIT]		COMPLETED
ELECTRICAL	41627	3/11/1997	APT. K10, REPLACE PANELS IN UNITS/INSP. + REPAIR ALUMINUM CIRCUITS [IF FOUND IN UNIT]		COMPLETED
ELECTRICAL	41628	3/11/1997	APT. K11, REPLACE PANELS IN UNITS/INSP. + REPAIR ALUMINUM CIRCUITS [IF FOUND IN UNIT]		COMPLETED
ELECTRICAL	41309	1/30/1997	INSTALL ONE WASHER OUTLET + DRYER OUTLET		COMPLETED
ELECTRICAL	39314	9/5/1996	INSTALL NEW DRYER AND WASHER OUTLET		COMPLETED
ELECTRICAL	39299	9/3/1996	REMOVE EXISTING ELECTRICAL DRY AND WASHER OUTLET		COMPLETED
ELECTRICAL	39211	8/19/1996	WALK THROUGH CK. TO CODE? - WASHERS, DRYER		COMPLETED
PLUMBING	39215	8/19/1996			PROCESSED
PLUMBING	27959	3/24/1993			COMPLETED
PLUMBING	27960	3/24/1993			COMPLETED
PLUMBING	27961	3/24/1993			COMPLETED
PLUMBING	27962	3/24/1993			COMPLETED
PLUMBING	27963	3/24/1993			COMPLETED
PLUMBING	27964	3/24/1993			COMPLETED

$\mbox{\ensuremath{\star}}$: Asterik after permit means there are notes on inspection

Thursday, June 29, 2023 Page 3 of 4

Туре	Permit No	Date	Full Description	Open Text	Status
PLUMBING	27965	3/24/1993			COMPLETED
PLUMBING	27966	3/24/1993			COMPLETED
PLUMBING	27967	3/24/1993			COMPLETED
PLUMBING	27968	3/24/1993			COMPLETED
GAS	23749	10/30/199	1		PROCESSED

$\ensuremath{^\star}$: Asterik after permit means there are notes on inspection

Thursday, June 29, 2023 Page 4 of 4