

Search... 

Record 22ENFCP-01561HS:
Enforcement - Housing Complaint
Record Status: Closed

[Add to collection](#)

Record Info ▾

Payments ▾

Work Location

64 CHEROKEE DR
Springfield MA 01109
United States

Record Details

Project Description:

Exterior
Vacant house with tarp on roof for over a year

Owner:

JOHNSON OSWALD D AND LUCILLE R
64 CHEROKEE DR
SPRINGFIELD MA 01109
United States

▼ More Details

☑ Related Contacts

Tenant information

*

64 CHEROKEE DR

☑ Application Information

COMPLAINT INFORMATION

Who should the inspector phone to get access?: anonymous complaint

Phone number for the inspector to call to gain access: n/a

Exterior: Yes

When did the problem first occur: 06/01/2021

Have you contacted the owner: No

Who did you contact: n/a

What was the response: n/a

Community Policing Sector: 11

Parcel Information

Parcel Number:
026970008
