

Permit			Inspection				Location	
Number	Type	Status	Type	Outcome	Date Scheduled	Inspector	Job Location:	
PRHV20090002414 Exchange of boiler	HVAC	Finaled	*Verify Final Review Status	Approved	08/31/2009	Mark Diciancia	21 GOODSELL STREET, West Hartford, CT 06107	
			Inspector Comments:	8/4/09 Boiler Replacement by Homeowner at 21 Goodsell St. MDC				Location Count 1
			*Issue Permit (Building)	Complete			Judy Kaufman	ADR 2381 1 21  0001 21GOODSE LLSTREET
			*Mechanical Review	Approved	08/31/2009	Mark Diciancia		
			*Mechanical Final Inspection	Failed	10/23/2009	Fred Falcone		
			Inspector Comments:	10/23/09 need to seal furnace flue at chimney, service switch needs cover FSF				
				Passed	10/30/2009	Jeff Reynolds		
			Inspector Comments:	10/30/09 Previous issues addressed. JAR				
PRRF20100004391 Strip and roof, fix new roof 16 sq timberline 30 years	Roofing-Siding	Issued	*Building Code Review	Approved		Jeff Reynolds	21 GOODSELL STREET, WEST HARTFORD, CT 06107	
			Inspector Comments:					Location Count 1
			*Verify Final Review Status	Approved	01/13/2011	Jeff Reynolds		
			Inspector Comments:					
			*Issue Permit (Building)	Complete		Judy Kaufman	ADR 2381 1 21  0001 21GOODSE LLSTREET	
			Inspector Comments:					
PRRF20140002502 Vinyl siding whole house and trim aluminum	Roofing-Siding	Issued	*Building Code Review	Approved		Jeff Reynolds	21 GOODSELL STREET, WEST HARTFORD, CT 06107	
			Inspector Comments:					Location Count 1
			*Verify Final Review Status	Approved		Jeff Reynolds		
			Inspector Comments:					
			*Issue Permit (Building)	Complete		Judy Kaufman	ADR 2381 1 21  0001 21GOODSE LLSTREET	
			Inspector Comments:					
PRZP09201500026 03 SHED PER PLAN	Shed	Issued					21 GOODSELL STREET, West Hartford, CT 06107	
							Location Count 1	

Permit			Inspection				Location
Number	Type	Status	Type	Outcome	Date Scheduled	Inspector	Job Location:
							ADR 2381 1 21  0001 21GOODSE LLSTREET