



CLICK HERE TO SIGN UP FOR BUILDINGS NEWS

NYC Department of Buildings

Overview for Complaint #:4163696 = CLOSED

Complaint at: 101-20 67 DRIVE BIN: <u>4075220</u> Borough: QUEENS ZIP: 11375

Re: EXCAVATION WORK BEING DONE UNDERMINING ADJACENT PREMISE

Category Code: 14 EXCAVATION - UNDERMINING ADJACENT BUILDING

Assigned To: QUEENS CONSTRUCTION ENFORCEMENT Priority: A

Received: 03/31/2003 08:23 Block: 3173 Lot: 21 Community Board: 406

Owner: A PADOVAN

Last Inspection: 04/02/2003 - - BY BADGE # 0415

Disposition: 04/03/2003 - C2 - INSPECTOR UNABLE TO GAIN ACCESS - 2ND ATTEMPT **Comments:** BLDG VACANT NEXT TO CONST FOR NB PERMIT#401248477 LS4 POSTED

Complaint Disposition History

#	Disposition		Dianosition	Inspection	Date
	Date	Code	Disposition	Ву	Date
2	04/03/2003	C2	INSPECTOR UNABLE TO GAIN ACCESS - 2ND ATTEMPT	0415	04/02/2003
			BLDG VACANT NEXT TO CONST FOR NB PERMIT#401248477 LS4 POSTED		
1	04/03/2003	C1	INSPECTOR UNABLE TO GAIN ACCESS - 1ST ATTEMPT	0415	03/31/2003
			ADJOINING PROPERTY VACANT 102-12 QUEENS BLVD NO ACCESS		

If you have any questions please review these <u>Frequently Asked Questions</u>, the <u>Glossary</u>, or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.