



 [CLICK HERE TO SIGN UP FOR BUILDINGS NEWS](#)

NYC Department of Buildings

Complaints By Address

Click [here](#) for information on how to remove a Stop Work Order from your property

Page: 1 of 1

Premises: 257 VAN DUZER STREET STATEN ISLAND

BIN: [5013392](#) Block: 507 Lot: 22

2 Total Complaints

[View Vacate Order Complaints](#) [View SWO Complaints](#)

Looking for a list of complaint [category codes](#) or [disposition codes](#)?
(Adobe Acrobat Reader required)

Complaint Number	Address	Date Entered	Category	Inspection Date	Disposition	Status
5049934	257 VAN DUZER STREET	04/05/2005	85	04/07/2005	I1	RES
	IMPROPER DRAINAGE IN THE BACKYARD OF ABOVE LOCATION CALLER STATED WHEN POOL IS BEING DRAINED WATER FLOWS ONTO THE ADJACENT PROPERTIES CAUSING DAMAGES AND FLOODING TO BASEMENTS					
5013795	257 VAN DUZER STREET	01/24/1994	73	02/10/1994	C2	CLS
	NO SECOND WAY OUT IN CASE OF FIRE. STEEL BARS UP TO WINDOWNO DOOR WHERE DOOR SHOULD BE					

If you have any questions please review these [Frequently Asked Questions](#), the [Glossary](#), or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.