



 [CLICK HERE TO SIGN UP FOR BUILDINGS NEWS](#)

NYC Department of Buildings

Complaints By Address

Click [here](#) for information on how to remove a Stop Work Order from your property

Page: 1 of 1

Premises: 118 CASSIDY PLACE STATEN ISLAND

BIN: [5095864](#) Block: 73 Lot: 7501

6 Total Complaints

[View Vacate Order Complaints](#) [View SWO Complaints](#)

Looking for a list of complaint [category codes](#) or [disposition codes](#)?
(Adobe Acrobat Reader required)

Complaint Number	Address	Date Entered	Category	Inspection Date	Disposition	Status
5148861	118 CASSIDY PLACE	05/25/2020	35	05/03/2021	I2	RES
	THERE IS EASEMENT BETWEEN TWO HOUSE AND THE SPACE IS BEING USED HAS AN ILLEGAL DRIVEWAY.					
5060329	120 CASSIDY PLACE	10/20/2006	05	10/27/2006	I2	RES
	ILLEGAL BUILT IN DECK INSIDE OF THE DRIVEWAY WITHOUT ANY PERMIT					
5060082	120 CASSIDY PLACE	10/05/2006	74	10/23/2006	I2	RES
	CLLR STS COMMERCIAL ACTIVITY IN RESIDENTIAL AREA BETWEEN THE HOURS 5PM TO 7PM (MACHINE SHOP)					
5058673	120 CASSIDY PLACE	07/25/2006	74	08/03/2006	I2	RES
	CALLER STATES THAT THERE IS A NEIGHBOR WHO IS CONDUCTING A CAR REPAIR BUSINESS IN A RESIDENTIAL NEIGHBORHOOD					
5058034	124 CASSIDY PLACE	06/21/2006	74	07/22/2006	I2	RES
	CALLER STATES THAT COMMERCIAL WORK IS BEING DONE IN RESIDENTIAL AREA. AUTO BODY WORK BEING DONE IN FRONT OF HOME					
5001366	124 CASSIDY PLACE	06/13/1989	15	06/22/1989	I2	RES
	OPEN CONSTRUCTION HOLE, FILLED WITH WATER AND IS UNFENCED					

If you have any questions please review these [Frequently Asked Questions](#), the [Glossary](#), or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.