

Bethlehem, PA 18016-0391 Phone (610) 866-9663 Fax (610) 866-2664

Wednesday, Jan 03, 2024

Windows must operate Remove rubbish - ext Ground outlets Repair kitchen

Walls/ceilings - repair

TP on WH

Rear porch - repair or replace Guard/handrail to basement GFCI protect basement outlets Upgrade to min 100 amp

Inspection Status Report

Page 4 of 5

Municipality: North Catasauqua Borough Inspections performed between 1/2/2024 and 1/2/2024

Owner	Address	Municipality	Contractor
Bryan Wa	atson 1120 Front Street	North Catasauqua Borough	OWNER
	CO Inspection	Tracking Number:	136855
Description:	Rental Inspections	PO Number:	CO Inspection
		Card Number:	A136855
		Permit Number:	CO Inspection
	(000434 P 1111 P 1 P 1 P 11 11	1 O	
V T A F	WH to vent per code Total rehab of ext property needed Attic - storage only Have roof checked - handrails	al (Not Approved - Suzanne Borzak)	
Y T A H S	WH to vent per code Cotal rehab of ext property needed Attic - storage only	al (Not Approved - Suzanne Borzak)	