

NYC Department of Buildings

**Complaints By Address**

Click [here](#) for information on how to remove a Stop Work Order from your property

Page: 1 of 2

Premises: 26-24 14 STREET QUEENS  
19 Total Complaints

BIN: [4020611](#) Block: 902 Lot: 34

[View Vacate Order Complaints](#) [View SWO Complaints](#)

Looking for a list of complaint [category codes](#) or [disposition codes](#)?  
(Adobe Acrobat Reader required)

Complaint Number	Address	Date Entered	Category	Inspection Date	Disposition	Status
<a href="#">4945080</a>	26-24 14 STREET	12/09/2023	45	01/04/2024	C1	ACT
<a href="#">4859958</a>	26-24 14 STREET	09/26/2021	45	11/07/2022	C2	CLS
<a href="#">4704470</a>	26-24 14 STREET	08/29/2017	05	11/30/2017	A8	RES
<a href="#">4704426</a>	26-24 14 STREET	08/29/2017	03	08/30/2017	I2	RES
	CONSTRUCTING STRUCTURE IN WALKWAY					
<a href="#">4695301</a>	26-24 14 STREET	06/17/2017	45	07/29/2017	C7	CLS
	THERE IS A TWO FAMILY HOUSE THATS BROKEN DOWN IN MORE APARTMENTS					
<a href="#">4541323</a>	2624 14 STREET	02/19/2013	45	07/21/2013	C2	CLS
	TOP FLOOR HAS ILLGAL DORMA, EXPANDED THE ROOF MADE A ROOM WITH A DOOR AND NO RAILING, 2ND FLOOR TO BASEMENT THEY BUILT AN EXTENSION 10X10, ILLEGAL BUNKER IN THE BASEMENT, KITCHEN IN BACK EXTENDS TO PL					
<a href="#">4486806</a>	26-24 14 STREET	07/05/2011	15	08/28/2012	I2	RES
	CALLER STS THE OWNER OF ABOVE ADDRESS IS PLACING AN ILLEGALFENCE TO BACK OF THE PROPERTY ALONG WITH DIGGING HUGE HOLES IN THE GROUND					
<a href="#">4480877</a>	26-24 14 STREET	05/13/2011	04	10/11/2011	I2	RES
	CALLER IS REPORTING UNAUTHORIZED AFTER HOURS CONSTRUCTION-WORK STARTS AT 6AM AND ENDS AFTER 6PM. THIS HAS BEEN A PROBLEM FOR 10MONTHS					
<a href="#">4469149</a>	26-24 14 STREET	01/07/2011	10	01/11/2011	C2	CLS
	CENTRAL AIR CONDITIONING UNIT INSTALLED AT THE ROOF IN THE BACK OF THE HOUSE/2 SUPPORTING BEAMS CUT FOR THIS INSTALLATION AND NO NEW SUPPORT BEAMS INSTALLED TO TAKE THEIR PLACE/UNSAFE STRUCTURE					
<a href="#">4469143</a>	26-24 14 STREET	01/07/2011	15	01/18/2011	A8	RES
	FRONT FENCE AT THIS LOCATION IS MORE THAN 7' HIGH					
<a href="#">4469141</a>	26-24 14 STREET	01/07/2011	45	01/11/2011	C2	CLS
	2 FAMILY HOUSE CONVERTED INTO 1 FAMILY/AFTER DOB INSPECTOR WAS ON SITE-OWNER MADE TEMP WALL & DOORS/TOTAL ILLEGAL PLUMBING & ELECTRICAL WORK DONE/NO PERMITS AT ALL WERE ISSUED BY DOB FOR THIS WORK					
<a href="#">4468589</a>	26-24 14 STREET	12/28/2010	05	12/22/2010	A8	RES
	WORK W/O PERMIT					
<a href="#">4468588</a>	26-24 14 STREET	12/28/2010	73	12/22/2010	A8	RES
	FAILURE TO MAINTAIN					
<a href="#">4468200</a>	26-24 14 STREET	12/20/2010	05	11/30/2010	A8	RES
	WORK WITHOUT A PERMIT					
<a href="#">4467731</a>	26-24 14 STREET	12/14/2010	45	12/22/2010	H1	RES
	POSSIBLE ILLEGAL CONVERSION OF BASEMENT					
<a href="#">4466729</a>	26-24 14 STREET	12/03/2010	45	12/22/2010	A8	RES
	FDNY REPORTED ILLEGAL OCCUPANCY THROUGHOUT					
<a href="#">4458045</a>	26-24 14 STREET	09/13/2010	05	09/22/2010	I2	RES
	CALLER STS INSIDE AND OUTSIDE CONSTRUCTION WORK IS BEINGDONE. THEY KNOCK DOWN THE BASEMENT AND ARE INPUTTING A DRYWELLTHE GARAGE HAS BEEN KNOCKED DOWN. ALSO, DAY LABORERS ARE DOING THE WOR					
<a href="#">4453859</a>	26-24 14 STREET	08/06/2010	05	09/22/2010	I2	RES
	CALLER STS A GARAGE AND A SHED IS BEING DEMOLISHED WITHOUT A PERMIT					

Next