

NYC Department of Buildings  
**Complaints By Address**

Click [here](#) for information on how to remove a Stop Work Order from your property

Premises: 135-10 35 AVENUE QUEENS  
 23 Total Complaints

BIN: [4112140](#) Block: 4959 Lot: 7501

[View Vacate Order Complaints](#) [View SWO Complaints](#)

Looking for a list of complaint [category codes](#) or [disposition codes](#)?  
 (Adobe Acrobat Reader required)

Complaint Number	Address	Date Entered	Category	Inspection Date	Disposition	Status
<a href="#">4937877</a>	135-10 35 AVENUE	09/20/2023	83	11/03/2023	I2	RES
	The neighboring property has built a scaffolding in the neighbor's parking lot without consent.					
<a href="#">4937309</a>	135-10 35 AVENUE	09/14/2023	73	09/01/2023	A1	RES
	EMERGENCY WORK ORDER DUE TO FAILURE TO PROTECT PUBLIC SAFETY					
<a href="#">4931032</a>	135-10 35 AVENUE	07/13/2023	2L	07/18/2023	RU	ACT
	UNSAFE NOTIFICATION SUBMITTED BY QEWI(PE/RA)INDICATING.....UNSAFE CONDITIONS ON EXTERIOR FACADE REFER TO LL FACADE UNIT.....FOR COPY OF NOTIFICATIN					
<a href="#">4852986</a>	135-10 35 AVENUE	07/23/2021	7J	07/24/2021	C2	CLS
	MY NEIGHBOR DID SOME ILLEGAL CONSTRUCTION UPSTAIRS WITH NOPERMIT POSTED AND NOW WHEN IT RAINS,IT HAS STARTED LEAKING INTO MYAPARTMENT SINCE THERE THERE IS NO WHERE FOR THE WATER TO GO, THEY					
<a href="#">4770380</a>	135-10 35 AVENUE	04/14/2019	45	04/18/2019	A8	RES
<a href="#">4765268</a>	135-10 35 AVENUE	03/05/2019	49	06/02/2022	J6	ACT
	IN A MIX BUILDING WHERE THE 1 FL IS A SENIOR CENTER . THE SENIOR CENTER BUILD A CANVAS /STORM ENCLOSURE THAT IS TAKING UP HALF OF THE SIDEWALK.					
<a href="#">4746639</a>	135-10 35 AVENUE	09/04/2018	05	12/10/2018	C2	CLS
<a href="#">4642836</a>	135-10 35 AVENUE	01/26/2016	63	04/12/2016	I2	RES
	CALLER STATES THAT THE ELEVATOR IS NOT WORKING FOR 21 DAYS WITH OUT A NOTICE.					
<a href="#">4556119</a>	135-10 35 AVENUE	08/09/2013	1Z	08/08/2013	A8	RES
	INTER-AGENCY REFERRAL					
<a href="#">4517751</a>	135-10 35 AVENUE	06/06/2012	45	08/25/2012	C2	CLS
	IN THE REAR OF SUBCELLAR THERE IS A SHEETROCK WALL DIVIDINGTHE SUB-CELLAR					
<a href="#">4475112</a>	135-10 35 AVENUE	03/21/2011	53	04/26/2011	I2	RES
	THE VENT OSN'T FUNCTIONING PROPERLY					
<a href="#">4438784</a>	135-10 35 AVENUE	03/27/2010	04	03/28/2010	I2	RES
	CALLER STS THERE'S CONSTRUCTION TAKEN PLACE AT THE GIVEN LOCATION W/O PERMITS STARTING BEFORE 6AM ON SATURDAY. REQUESTING INSPECTION					
<a href="#">4435872</a>	135-10 35 AVENUE	03/02/2010	45	03/08/2010	I2	RES
	ILLEGAL CONVERSION APPOINTMENT ON 3/8 @ 10 AM					
<a href="#">4419359</a>	135-10 35 AVENUE	10/11/2009	45	02/28/2010	C2	CLS
	CALLER STATES THAT 2 ROOMS ON THE FIRST FLOOR ARE BEING RENTED OUT AS SINGLE ROOM OCCUPANCIES					
<a href="#">4413456</a>	135-10 35 AVENUE	08/28/2009	83	08/31/2009	I2	RES
	D-14 AUDIT (420056762)					
<a href="#">4413457</a>	135-10 35 AVENUE	08/28/2009	83	08/31/2009	I2	RES
	D-14 AUDIT (410169437)					
<a href="#">4413323</a>	135-10 35 AVENUE	08/27/2009	83	09/14/2009	A1	RES
	D-14 AUDIT (402557032)					
<a href="#">4370679</a>	135-10 35 AVENUE	09/06/2008	09	09/12/2008	L2	RES
	CALLER STATES TAHT THERE IS EXCESSIVE DEBRIS AT CONSTRUCTION SITE THAT IS DIRECTLY ACCROSS FROM ADDRESS ABOVE					

If you have any questions please review these [Frequently Asked Questions](#), the [Glossary](#), or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.