Los Angeles Department of Building and Safety

The information below was found on the following Parcel Identification Number (PIN):

171B117-109		upo super	
Parcel Profile Report:	to the state of th		(1)
Permit Information four			(1)
Code Enforcement Information:			(2)
Date Received	Problem Description	Status	
10/6/2009	POOL WATER NOT KEPT CLEAN	CLOSED	
9/20/2023	POOL WATER NOT KEPT CLEAN	UNDER INVESTIGATION	
Agrico Indiana	- the state of the	As the state of th	and and a

Los Angeles Department of Building and Safety

Code Enforcement Information: 5319 N BOTHWELL ROAD

Date Received: Description:

9/20/2023

POOL WATER NOT KEPT CLEAN

Inspector:

ROBERT SUNSERI (818)374-9857

UNDER INVESTIGATION

Order Information

Order Number

Order Type

Effective Date

Issued By

Phone

NOTICE OF CODE VIOLATION

10/12/2023

EMIL ALEXANDRIAN

(818)374-9863

Code Violation Information

Violation

Date in Compliance

The recirculation and purification system of the swimming pool has not been operated and/or maintained so as to keep the water clean and of reasonable clarity.